S			3-03424A0024000200 //-323	58-2 56 B
TO :	CONFIDE Chief, Procurement Division, LO	NTIAL 3	4 January 1954	
FROM:	Chief, Engineering Division, OC			
Surject:	PSC-148-UNV 51-3178	Consigner: Consignee:	Group #5	25X1
	1. An inspection by the Test & Evaluation Section of 10 each, RS-6 Radio Sets reveals that they are all rejected. 2. Listed below are the serial numbers of the rejected units with reason for rejection: 5337 - Low output low end of high band (transmitter) 5359 - BFO operates continuously (receiver) 5370 - Defective BFO (receiver) 5418 - BFO operates continuously (receiver) 5423 - Defective crystal socket (receiver) 5430 - Inoperative on crystal operation at 15 mc. (receiver) 5437 - Inoperative on crystal operation at 15 mc. (receiver) 5442 - Low output on low end of high band (transmitter) 5525 - Leaky oil filled condenser (adaptor) 5540 - Power transformer burns. Vibrator runs on AC operation (power supply) 3. It is suggested that the rejected units be returned to the contractor for replacement or repair.			
	FOR THE CHIEF, ENGINEERING DIVI	SION:		
				25 X 1
	OC-E/TRE/HBM/dd (14 January 1954)			
	Distribution: 1 - Courtesy 1 - Eng/C&ERB 1 - Reading 1 - Chrono 1 - Receiving 1 - MSB		•	25 X 1
	1 - R&D Ext.Proj. ~ 1 - Suspense 1 - T&E Ref. No. 01648			

STEEL COMMUENTIAL